

GEIGER COUNTER

RADEX RD1503



CE

CONTENTS

Precautions to be taken before use	3
Presentation of the Radex Geiger Counter	4
Information on radioactivity	4
Threshold levels of radioactivity	5
Calculation of average doses	5
Layout of the Radex Geiger Counter	6
LCDscreen	7
Summary	9
Positioning of batteries	11
How to use the menu	12
How to change the measurement units	13
Alert threshold	14
Settings	15
After sales service	17
Information	17
Potential faults	17
Instructions for use	18
How to carry out measures correctly	20
Effects of radioactivity	21
Natural irradiation	21
Artificial irradiation	22
Contamination and concentration	23
The units	24
Technical features	25
Common radioactive objects	26
Guarantee	29

PRECAUTIONS TO BE TAKEN BEFORE USE

- > Regularly check that the batteries are in good working order. If the screen indicates nothing or 0 or 1 $\mu\text{Rem/h}$, you need to change the batteries. Remove them from the counter if it is unused for a long period of time.
- > Do not open the casing, the detection tube is under high voltage
- > The counter is not water proof and must therefore not be used in rain or placed in water. If water happens to seep into the counter, you must switch it off, wipe it with a soft piece of fabric and put it in a warm and dry place to dry out the inside of the counter.
- > Do not knock or drop the counter and keep from dust and humidity.
- > Do not allow aggressive chemical substances like acids, alkali, solvents etc...to drop on the counter and avoid places where these substances can be found.
- > Do not wipe with abrasives
- > Do not place the counter in a micro wave oven and do not place it near an ionizer or ozone generator which has been switched on.
- > Do not expose the counter to direct sun or fluorescent light for any length of time.
- > Do not allow foreign bodies to penetrate the counter through its openings.
- > The accuracy of the counter is compatible with domestic use. In the event of extremely abnormal detection, call a specialised organisation.
- > If the counter has been stored in a cold place, leave it at room temperature for at least one hour to avoid condensation.
- > Do not use the counter otherwise than in the stipulated environment.

PRESENTATION OF THE RADEX GEIGER COUNTER

The Radex Geiger counter RD1503 is a particularly sensitive detector of *Beta** particles, and *X** and Gamma rays (called ionizing rays). It measures the *Beta** particles and ionizations created by *X** and Gamma rays in 10 second cycles to indicate the 'quantity of energy' transmitted to matter over a certain amount of time. However, the Geiger counters cannot identify the different radioactive elements.

The measurement units which are used are micro Rems per hour ($\mu\text{Rem/h}$) or micro sieverts per hour ($\mu\text{Sv/h}$). They correspond to the dose received by the human body over a period of one hour.

INFORMATION ON RADIOACTIVITY

Matter is made up of atoms. Each atom consists of a nucleus which is surrounded by neutrons which gravitate around it like satellites.

Radioactive substances spontaneously produce Gamma or X and/or Beta particles or sometimes Alpha particles.

Beta particles are electrons. Because of their charge, they react very strongly to matter. They can travel from a few centimetres to a few metres through the air. A sheet of aluminium can stop them.

Alpha particles are helium nuclei (2 protons and 2 neutrons). They can travel a few centimetres through the air. A sheet of paper can stop them.

Gamma rays are electromagnetic rays formed during physical phenomena which take place within the nucleus of the atom. Gamma rays can produce ions directly or indirectly (ions are atoms or molecules with an electric charge which is not nil) while they travel through matter. They can travel dozens of metres through the air. A thick quantity of lead and concrete can significantly reduce their impact.

* : Tested by the LCIE

X rays are similar to Gamma rays but are created during physical phenomena happening at the level of the electronic procession of the atom. They are used in medicine and can rarely be found in nature.

THRESHOLD LEVELS OF RADIOACTIVITY

There is no threshold under which radioactivity is harmless. Any dose, even very slight, causes a health hazard. The greater the dose is, the greater the risk of cancer or genetic anomaly. The relation between the risk and the dose is considered to be linear. Indeed, the International commission on Radiological protection (ICRP) proposed in 1990 that the equivalent of the maximum dose should be of one millisievert per year, that is to say $11.4\mu\text{Rem/h}$ on average. This norm concerns doses other than those due to medical examinations or natural radioactivity. The former norm which is still occasionally used was of 5millisieverts per year but it included all of these different types of radiation. The ICRP estimates that each millisievert is responsible for 60 extra cancers (50 of which are lethal) and 13 genetic anomalies per million persons.

CALCULATION OF AVERAGE DOSES

You must take into account the radiation levels corresponding to the places you are usually in and the amount of time you usually spend there in order to calculate an average dose.

Example:

Dwelling: $20\mu\text{Rem/h}$, 12 hours a day


Work place: $30\mu\text{Rem/h}$, 8 hours a day.

Other places: $10\mu\text{Rem/h}$, 4 hours a day.

Average dose = $(20 \times 12) + (30 \times 8) + (10 \times 4) = 520 \mu\text{Rem}$ for 24 hours.

Therefore $520 \div 24 = 21.6 \mu\text{Rem/h}$


LAYOUT OF THE RADEX






1. Liquid crystal display (LCD)
2. 'Menu' button with its icon displayed on the screen. The button has three functions: 'menu', 'choose', 'change'.
3. The 'cursor' button with its icon displayed shift on the screen. This button will be used in the menu as a cursor.
4. The ' ON/OFF' button. The button has 4 functions. It enables you to: switch the counter on, light up the LCD, backtrack in the menu, switch the counter off.
5. Battery compartment
6. Geiger Muller tube

The icons indicate the function of each button to the user, making it thus very easy to use. The icons will be described in detail below.

LCD SCREEN



1. Icon showing state of batteries :




-  - Fully charged batteries
-  - Run down batteries
-  - Replacement of batteries needed

2. Units :




-  -micro Sievert per hour
-  -micro Roentgen per hour

3. Icon showing the sound alarm threshold levels.

With $\mu\text{Sv/h}$:

-  -0,30 $\mu\text{Sv/h}$
-  -0,60 $\mu\text{Sv/h}$
-  -1,20 $\mu\text{Sv/h}$



With $\mu\text{Rem/h}$:

-  -30 $\mu\text{Rem/h}$;
-  -60 $\mu\text{Rem/h}$;
-  -120 $\mu\text{Rem/h}$.

Or

-  -Alarm is deactivated

4. Icon showing sound alarm

-  - Sound alarm activated (high or low level)
-  - Sound alarm is deactivated

5. Backlight icon :



- Backlight on



- Backlight off

6. Functions of 'ON/OFF' button (see page 6)

7. Measurement results ($\mu\text{Sv/h}$ or $\mu\text{Rem/h}$)

8. Functions of the 'CURSOR' button (see page 6)

9. Functions of the 'MENU' button (see page 6)

10. The icon showing the number of measurement cycles carried out:



- corresponds to the first short measurement cycle



- corresponds to the second short measurement cycle



- corresponds to the third short measurement cycle



- corresponds to one measurement cycle



- corresponds to two measurement cycles



- corresponds to three measurement cycles



- correspond to four or more measurement cycles.

The display of the square in the centre of the screen means that ionizing rays have been detected.

11. Indication of recorded particles

SUMMARY

1

Positioning of batteries


Place two or one 'AAA' battery in the battery compartment. The polarity of the contacts (+ or -) are indicated in the compartment.



2

Switching the counter on and off.


To switch the counter on, press on the big button. The message 'RD1503' will then appear on the screen. To switch the detector off, press on the same button for a long time.



3

Results

The first measurements (dose debit) will be displayed within ten seconds.



4

Enter the menu

Press on the ' Menu' button.
The contents of the menu will appear. If not modified , the following features apply:
Measurement units - $\mu\text{Sv/h}$
Alert level -0.30 $\mu\text{Sv/h}$
Audio -low
Lighting -Off



5

Choice of menu

The movements of the cursor in the menu are done with the 'Cursor' button. The selection of choices is done with the 'Menu' button.




6

Leaving the menu.

To leave the menu use the 'OFF' button.
To switch the counter off press on the 'OFF' button until messages on the screen are no longer displayed.



INSTALLATION OF BATTERIES




1. Remove the lid of the battery compartment (1),
2. Insert two 'AAA' battery in the battery compartment (3)
3. Replace the lid on the battery compartment.

NB :

- 1. To carry out long measurements we recommend use of two batteries. For short measurements you can use only one battery.***
- 2. Do not use an old battery with a new one.***
- 3. Remove the batteries if you do not need to use the counter for a long time.***

HOW TO USE THE MENU.

The menu enables the user to make certain choices. Measurements are established on entering the menu and re-established on quitting the menu.



To enter the main menu, press on the 'MENU' button.

The word 'Menu' and a reference number will appear.

A cursor will appear in front of the first item in the menu.


To choose an item, press on the 'CHOISIR' button.

To move on to another item on the menu, use the button to move the cursor.

To quit the menu use the 'RETOUR' button.

All the choices made in the menu are saved after the counter has been switched off.

CHANGING THE MEASUREMENT UNITS



1. Place the cursor on 'UNITES'. Press on the 'choisir' button and screen number 2 will appear.
2. Select the measurement unit with the cursor and the symbol. Validate with the 'CHANGER' button.
3. To return to the main menu, press on the 'RETOUR' button.

ADJUSTMENTS

The 'REGLAGE' section enables you to make adjustments to the sound alarm and the lighting.



Adjustments to the lighting

1. Place the cursor in 'REGLAGE' and press on the button 'CHOISIR'. Screen number 2 will appear.
2. Select 'ECLAIRAGE' with the cursor. Validate with the 'CHOISIR' button. Screen number 2 will appear.
3. Select 'ON' or 'OFF' button depending on whether you want to have your LCD lit up or not. Validate with the button 'CHANGER'.
4. To return to the main menu, press twice on the button 'RETOUR'.

The lighting of the LCD is activated by pressing the big button if the function 'ECLAIRAGE' enables you to (that is to say, if you have previously selected 'ON'). The lighting is activated for approximately 3 seconds. To prolong use of lighting, you must press the big button several times. The lighting enables you to see the LCD in the dark. In day time the use of lighting is not necessary.

Please note that the use of lighting greatly reduces the autonomy of the counter.

Adjustments to the sound alarm



1. Place the cursor on 'REGLAGE', press the button 'CHOISIR'.
Screen number 2 will appear.
2. Select 'AUDIO' with the cursor and the symbol. Validate with the button 'CHOISIR'. Screen number two will appear.
3. Select 'HAUT', 'BAS', 'SILENCE' with the cursor.
Validate with the button 'CHANGER'.
4. To return to the main menu, press twice on the button 'RETOUR'.

AFTER SALES SERVICE

The 'SAV' section indicates the telephone number of our after sales service in France


1. Place the cursor on 'SAV'. Press on the button 'CHOISIR'.
2. To return to the main menu press on the button 'RETOUR'.

INFORMATION

The section 'INFOS' indicates the Web site of NanoSense where you will find information and links on radioactivity.

1. Place the cursor on 'INFOS'. Press on the button 'CHOISIR'.
2. To return to the main menu press on the button 'RETOUR'.

POSSIBLE FAULTS

Possible fault	Possible cause of breakdown	Corrective action
No display on screen when counter is switched on.	Batteries have not been or are incorrectly positioned.	Insert the batteries correctly. Check polarities (+/-)
Message on LCD 	Batteries running low or empty.	Replace the batteries.

HOW TO USE YOUR COUNTER

Switching the counter on

To switch the counter on, press the big button, the screen will display 'RD1503'.

Measurements

The counter starts to count the ionizing rays as soon as it is switched on. During the measurement cycles, each ionisation is recorded and accompanied by an icon and a short sound signal (if the sound option has been activated and the threshold level option deactivated).





The display of the icon on the LCD is proportional to the dose. 10 seconds after switching the counter on, the first result of the short measurement cycle and an icon appears:



- -Corresponds to a first short measurement cycle
- -Corresponds to a second short measurement cycle
- -Corresponds to a third short measurement cycle


The second and third short measurement cycles average out with the previous cycles.

* The short measurement cycle lasts 10 seconds. It is meant to rapidly provide you with a first result. A more reliable result will be obtained after a first measurement cycle of 40 seconds indication, a first numerical result will indicate the quantity of ionizing rays detected and the side of a square will appear :

- |  - Corresponds to one measurement cycle
- |  - Corresponds to two measurement cycles
- |  - Corresponds to three measurement cycles
- |  - Corresponds to four measurement cycles.



- The first measurement result displayed is equivalent to the average value of 4 short cycles.
- The second result displayed is equivalent to the average value of two measurement cycles.
- The third result is equivalent to three measurement cycles and all the following results are equivalent to the average of the 4 preceding results.

In order to calculate the average, the counter analyzes the variations of the raw values in relation to the results of the previous measurements. If the acceleration exceeds a predetermined value, the last raw result will be given instead of the average. For example, if the result of three measurements averages at $0.20\mu\text{Sv/h}$ and the raw value of the fourth cycle is $0.80\mu\text{Sv/h}$, the result of the fourth measurement will not represent an average of the 4 previous cycles and so, $0.80\mu\text{Sv/h}$ and the icon |  will appear. This function will enable you to quickly detect rapid changes in the level of radiation.

Switching the counter off

To switch the counter off, press on the big button 'OFF' and keep button pressed down until all messages disappear from the screen.

HOW TO CARRY OUT MEASURES CORRECTLY ?

Because of the statistical nature of radioactivity, the average value of at least 5 measures carried out under the same conditions can be considered to be of interest, especially in the case of low levels.

The ambient atmosphere is subject to significant fluctuations from one measurement cycle to another. First, measure the level of radiation which provides 'the background noise'. You can then analyze actual objects: position the left side of the counter which has openings close to the object which is potentially emitting β or γ rays. If the measurement exceeds the 'background noise' level, the object is radioactive and the Radex Geiger counter will enable you to estimate the dose debit when in contact with or at a distance from the object. If the measurement is equal to that of the 'background noise you can, on the basis of a first analysis, consider that the object is not radioactive. It is however possible that it contains radioactive elements emitting β or γ rays but in too feeble an intensity to emerge from the 'background noise'. These elements are generally radiotoxic if ingested.

In the event of radioactive contamination of liquids, the measurement of the dose is carried out above the uncovered surface of the liquid. The liquid must not come into contact with the surface of the counter and must not penetrate it. It is recommended that a polythene bag be used, but not more than one layer, to protect the counter.

To detect an occasional source of radiation, it is best to rely on the sound signals emitted by the counter.

It is possible to distinguish β from γ rays by using a filter. A measurement taken without a filter, is the sum of $\beta + \gamma$ rays. With a filter, like a sheet of aluminium (foil paper), the measurement is of the γ rays only. The difference is thus the quantity of β rays.

EFFECTS OF RADIOACTIVITY

The ionization of the molecules in the human body can cause disorders capable of causing cancerous tumours and genetic mutations likely to create hereditary abnormalities.

Parts of the body most sensitive to radiation (in decreasing order)

- 1) The reproductive glands of both sexes (hereditary abnormality)
- 2) Breasts (cancer)
- 3) Red bone marrow (leukaemia)
- 4) Lungs
- 5) Thyroid gland
- 6) Bones
- 7) Muscle tissue
- 8) Skin

NATURAL IRRADIATION

Sedimentary soil :	4 μ Rem/h on average (according to the region)
Granitic soil :	20 times more than sedimentary soil (radioactivity of 8000Bq/kg)
Radon :	This gas is a product of uranium which migrates through the soil and stagnates in dwellings. It emits Alpha particles and some Gamma rays.
Cosmic rays* :	3.4 μ Rem/h at sea level (10.3 to 3000m)
The human body :	2.3 to 17.7 μ Rem/h (linked with ingestion and inhalation)
Water and food :	5,7 μ Rem/h (non contaminated products)


ARTIFICIAL IRRADIATION

Medical :	11.4 μ Rem/h average/year (x rays, radiotherapy)
-----------	--

T.V screen : 0,11 μ Rem/h
Nuclear tests : 51.3 μ Rem in 50 years (average diluted atmospheric fallout)

Etc


* Cosmic rays are reduced by the atmosphere, their effects are thus increased with altitude. The level can reach 300 μ Rem/h in an plane at an altitude of 10 000 m, especially near the North or South Pole.



Average natural radiation levels per region in micro Rem/h

CONTAMINATION AND CONCENTRATION

The following diagram illustrates in a simple way how radioactive elements are propagated and how they can be concentrated in food. Beware, game such as migrant birds (ducks, woodcocks.) can be radioactive as most of them come from Eastern Europe where numerous contaminated zones are to be found.



UNITS

UNITS	EQUIVALENT	DEFINITION
Curie (Ci) or Becquerel (Bq)	1 Curie = 37 billion Becquerels 1 Becquerel = 27 pico-curies	Measures the number of disintegration per second (ACTIVITY)
Roentgen (R)	1 Roentgen = $2,58 \cdot 10^{-4}$ C/Kg	Measures the energy in the air (DOSE)
Rad (Reontgen absorbed dose) or Gray (Gy)	1 Gray = 100 Rad (1 joule/Kg) 1 Rad = 0,01 Gy	Measures the energy received per mass unit (ABSORBED DOSE)
Rem (Rad Equivalent Man) or Sievert (Sv)	1 Rem = 10 milli Sievert (mSv) 1 Sv = 100 Rem ~ 100 R	Effect of the radiations on the human body (EQUIVALENT OF EFFICIENT DOSE)

TECHNICAL FEATURES

Ionizing radiations detected :	X Rays, Gamma rays and Bêta particles (X, β and γ)
Measurement cycle :	40 seconds +/- 0.5s
Measurement units :	μ Rem/h or μ Sv/h
Sensor :	Geiger-Müller tube
Display :	3 digits + cycle symbols on LCD
Measurement range in μ Rem/h :	5 to 999 μ Rem/h
Measurement range in μ Sv/h :	0,05 to 9,99 μ Sv/h
Alarm thresholds :	
- in μ Rem/h	30, 60, 120
- in μ Sv/h	0,3; 0,6, 1,2
Energy of the detected X and γ rays :	0,1 to 1,25 MeV
Energy of the detected β particles :	350 keV to 1,5 MeV
Runs on :	1 or 2 AAA batteries
Range of temperature for the storage :	+5°C to + 40°C
Range of temperature for the use :	-20°C to + 50°C
Range of humidity :	Less than 80%RH at 25°C
Autonomy :	550 hours
Weight (without batteries)	90g

COMMON RADIOACTIVE OBJECTS

Alarm clocks and watches

Twenty years ago the hands of an alarm clock or watch were luminescent. The substance used were usually Radium or other radioactive substances. Measurements taken next to the face of an alarm clock or watch can reach $600\mu\text{Rem/h}$. It is best to avoid wearing such a watch.

Gas lamp incandescent mantles

When camping you might have used gas lamps. A mantle is adapted to the lamp and once heated by the gas, it will emit light by incandescence.

Levels of irradiation:

Levels measured vary from 15 to $360\ \mu\text{Rem/h}$ when in direct contact. At distances exceeding 50 cm, rays are no longer detected.

You can protect yourself from radiations by keeping at a distance of more than 50 cm. from a mantle. Avoid putting a mantle in your pocket.

Lightning conductors

Fifty years after Benjamin Franklin discovered the lightning conductor in 1760, a Hungarian thought of placing a radioactive source at the tip of a lightning conductor. He thought that the radioactivity would ionize the air around the tip of the lightning conductor and make it conductive and that thunder bolts would in consequence be directed there.

Although the efficiency of this process was uncertain, it was patented and commercialized in 1932.

It is thought that approximately 30 000 radioactive lightning conductors still stand on our roofs in France. In 1983 a decree forbade the use of radioactive elements in the manufacture of lightning conductors, leaving a period of 4 years for manufacturers to comply. In 1986 a new decree also forbade the import and sale of such lightning conductors.

The risks

The radionuclides used are extremely radiotoxic and the period of radioactivity lasts for a very long time. The sources remain radioactive for years, sometimes thousands of years. For example, the radioactive period of

Americium 241 is of 433 years. This is the amount of time it takes for radioactivity to be reduced by half. It can be calculated that for a source of 30 million Becquerels in 1987, there will be 15 million in 2420; 7.5 million in 2863 and 3.7 million in 3296 etc...


The radioactive period of Radium 226 is much longer: 16000 years. The rate at which it diminishes is thus much slower. Radioactive sources used in lightning conductors are thus going to remain dangerous for generations. It is important to look after their removal and place of storage to limit risks of dispersion.




Franklin France



Duval Messien



Helita



GUARANTEE

The counter is guaranteed against all manufacturing faults and material defects within the limits of the following terms:

- The guarantee is strictly limited to the exchange or repair of parts which have been found faulty after examination and control in our factory, to the exclusion of any other form of indemnity.
- The period of guarantee is of one year starting on the date of purchase.
- The guarantee for spare parts and labour is valid on the condition that the counter has been used correctly and in compliance with the instructions given by the manufacturer
- The guarantee does not cover deteriorations or accidents due to negligence or modifications or attempts to modify the counter in any way.
- The guarantee does not cover incidents due to fortuitous or unavoidable major events unconnected with the manufacturer, or deterioration due to normal 'wear and tear' of the counter.
- The guarantee ceases to be valid if the buyer has opened or attempted to open the casing.
- The guarantee only covers counters which have been sent back to the retailer with a copy of the invoice.
- The cost of sending the counter to the retailer must be covered by the buyer.
- Time spent repairing the counter while under guarantee does not prolong the period of guarantee.
- The terms of the present guarantee do not prevent the buyer from benefiting from the advantages of the legal guarantee (Article 1641 and following of the Code civil) afforded in the event of hidden faults and defects.

Before sending the counter back, check that the batteries have been correctly inserted: this is the most common problem.